

CAR INSPECTION REPORT

Certified by Al Shaheen Auto Hub Technical Evaluation Team



Mazda Flair XS 2022

OVERALL RATING

9.9 /10

CAR DETAILS

CUSTOMER/DEALER NAME

Al Shaheen Auto Hub

ENGINE CAPACITY

660

MILEAGE

32755

TRANSMISSION TYPE

Automatic

INSPECTION DATE

30 Aug 2026

CHASSIS NO

MJ95S-120033

ENGINE NO

R06D

REGISTRATION NO

IMPORT

FUEL TYPE

Hybrid

COLOR

Red

LOCATION

Lahore

REGISTERED CITY

Punjab

SUMMARY

Overall Rating: 9.9/10

ENGINE / TRANSMISSION / CLUTCH

100%

BRAKES

100%

SUSPENSION/STEERING

100%

INTERIOR

98%

AC/HEATER

100%

ELECTRICAL & ELECTRONICS

100%


EXTERIOR & BODY

87%

TYRES

100%

EXTERIOR CONDITION



LEGEND

P:

Paint marked

A2:

Scratch

U1:

Small Dent

U3:

Big Dent

B2:

Dent with scratch (palm)

H:

Paint faded

DOT:

Minor Scratches/Dents

A1:

Small Scratch

A3:

Big Scratch

U2:

Dent

B1:

Small dent with scratch (th...

S1:

Rust

E1:

Few Dimples

BODY FRAME ACCIDENT CHECKLIST				100%
Radiator Core Support	OK	Left B Pillar	OK	
Right Strut Tower Apron	OK	Right C Pillar	OK	
Left Strut Tower Apron	OK	Left C Pillar	OK	
Right Front Rail	OK	Right D Pillar	Ok	
Left Front Rail	OK	Left D Pillar	Ok	
Cowl Panel Firewall	OK	Boot Floor	Ok	
Right A Pillar	Ok	Boot Lock Pillar	Ok	
Left A Pillar	OK	Rear Sub Frame	OK	
Right B Pillar	OK	Front Sub Frame	OK	

ENGINE / TRANSMISSION / CLUTCH100%

Engine Oil Level	Ok	Engine Vibration	No Vibration
Engine Oil Leakage	No Leakage	Cold Start	Ok
Transmission Oil Leakage	No Leakage	Engine Mounts	Ok
Coolant Leakage	No Leakage	Pulleys (Adjuster)	Ok
Brake Oil Leakage	No Leakage	Hoses	Ok
Belts (AC)	Ok	Exhaust Sound	Ok
Belts (Fan)	Ok	Radiator	Ok
Wires (Wiring Harness)	Ok	Suction Fan	Working
Engine Blow (Manual Check)	Not Present	Starter Operation	Ok
Engine Noise	Excellent		

BRAKES100%

Parking / Hand Brake	Ok		
----------------------	----	--	--

SUSPENSION / STEERING100%

Steering Wheel Play	Ok	Front Left Bushes	Ok
Right Ball Joint	Ok	Front Right Shock	Ok
Left Ball Joint	Ok	Front Left Shock	Ok
Right Tie Rod End	Ok	Rear Right Bushes	No Damage Found
Left Tie Rod End	Ok	Rear Left Bushes	Ok
Front Right Boots	Ok	Rear Right Shock	Ok
Front Left Boots	Ok	Rear Left Shock	Ok
Front Right Bushes	Ok		

INTERIOR

98%

Steering Wheel Condition	Ok	Interior Lightings	Ok
Horn	Working	Dash Controls - A/C	Working
Lights Lever / Switch (High/Low, Indicators)	Working	Dash Controls - De-Fog	Working
Wiper / Washer Lever (Speeds)	Working	Dash Controls - Hazard Lights	Working
Right Side Mirror	Working	Dash Controls - Others	Working
Left Side Mirror	Working	Audio/Video	Working
Right Seat Adjuster Recliner	Working	Rear View Camera	Working
Left Seat Adjuster Recliner	Working	Trunk Release Lever / Button	Working
Right Seat Adjuster Lear Track	Working	Fuel Cap Release Lever / Button	Working
Left Seat Adjuster Lear Track	Working	Bonnet Release Lever / Button	Working
Right Seat Belt	Working	Roof Poshish	Ok
Left Seat Belt	Working	Floor Mat	Perfect
Rear Seat Belts	Working	Front Right Seat Poshish	Ok
Glove Box	Working	Front Left Seat Poshish	Ok
Front Right Power Window/Lever	Working Properly	Rear Seat Poshish	Not Checked (Cover)
Front Left Power Window/Lever	Working Properly	Dashboard Condition	Minor Spots
Rear Right Power Window/Lever	Working Properly	Tools	Complete
Rear Left Power Window/Lever	Working Properly	Jack	Present
Window Safety Lock	Working	Puncture Repair Kit	Present

AC / HEATER

100%

AC Fitted	Yes	Cooling	Excellent
AC Operational	Yes	Heating	Excellent
Blower	Excellent Air Throw		

ELECTRICAL & ELECTRONICS

100%

Computer Check up / Malfunction Check	Ok	Key Fob Battery Low Light	Not Present
Battery Warning Light	Not Present	Voltage	12 V
Oil Pressure Low Warning Light	Not Present	Terminals Condition	Ok
Temperature Warning Light / Gauge	Not Present	Charging	Ok
Air Bag Warning Light	Not Present	Alternator Operation	Ok
Power Steering Warning Light	Not Present	Gauges	Working
ABS Warning Light	Not Present		

EXTERIOR & BODY

87%

Trunk Lock	Ok	Right Headlight (Working)	Working
Front Windshield Condition	Ok	Left Headlight (Working)	Working
Rear Windshield Condition	Ok	Right Headlight (Condition)	Working
Front Right Door Window	Ok	Left Headlight (Condition)	Working
Front Left Door Window	Ok	Right Taillight (Working)	Working
Rear Right Door Window	Ok	Left Taillight (Working)	Working
Rear Left Door Window	Ok	Right Taillight (Condition)	Working
Windscreen Wiper	Working	Left Taillight (Condition)	Working

TYRES

100%

Front Right Tyre Brand	Ok	Rear Left Tyre Brand	Ok
Front Right Tyre Tread	Ok	Rear Left Tyre Tread	Ok
Front Left Tyre Brand	Ok	Tyre Size	Ok
Front Left Tyre Tread	Ok	Rims	Alloy
Rear Right Tyre Brand	Ok	Wheel Caps	Ok
Rear Right Tyre Tread	Ok		

TEST DRIVE EVALUATION

100% Verified

Engine Pick	Ok	Steering Operation (While Driving)	Smooth
Drive Shaft Noise	No Noise	Steering Wheel Alignment (While Driving)	Centered
Gear Shifting (Automatic)	Smooth	AC Operation (While Driving)	Working
Brake Pedal Operation	Timely Response	Heater Operation (While Driving)	Perfect
ABS Operation	Timely Response	Speedometer (While Driving)	Working
Front Suspension (While Driving)	Ok	Test Drive Done By	Seller
Rear Suspension (While Driving)	No Noise		

Inspector Conclusion & Recommendation:

Vehicle inspection initialized by Al Shaheen Auto Hub certified evaluator.

Certified Inspector:
Mr. Haider

Inspection Stamp:
AL SHAHEEN CERTIFIED

DISCLAIMER:

In case of any query or concern regarding inspection please call 0344 1411123 or 042-35732222. This report is based on the condition of the vehicle on the date of certification and provides an approximate expert estimate. Except where indicated, parts were in working condition - this report does not take into account parts not visible or not inspected without disassembly. Al Shaheen Auto Hub has relied on the odometer reading as seen at the time of inspection and is not liable for tampering prior to inspection. Unless mentioned by the dealer or seller, vehicles with repainted panels are measured using digital coating thickness gauge. All reports are subjective professional assessments.



Front View



Oblique Front - Right



Oblique Rear - Right



Rear View



Oblique Rear - Left



Oblique Front - Left

INSPECTION PHOTO EVIDENCE • PAGE 2 OF 2

Mazda Flair XS - IMPORT




Odometer



Engine Compartment



Front Interior



Rear Interior



Tool kit / Spare tyre



Trunk Open